

WALCHA SEWAGE TREATMENT PLANT (STP) - EPL 2613 POLLUTANT LOCATIONS / SITE INFRASTRUCTURE



WALCHA SEWAGE TREATMENT PLANT (STP) - EPL 2613 Emergency Equipment & Evacuation Muster Point



FIREFIGHTING WATER

NO HYDRANT FOR CONNECTION TO RETICULATED WATER SUPPLY AT THIS SITE

TERTIARY POND /
LAGOON to north is
suitable for firefighting
water supply if direct skin
contact is minimised and
hoses / equipment
flushed after use.

LAGOONS at east of plant are not considered suitable for firefighting as high sludge levels may be present at times.


PLANT / EQUIPMENT

No heavy plant items based permanently at this site.

Portable (trailer mount)
pumps and ancillary
sewer maintenance items
available for on / offsite
use if required.



WALCHA SEWAGE TREATMENT PLANT - EPL 2613 FLOW PATH (THROUGH PLANT) AND SITE DRAINAGE



LEGEND

- >>> Formed discharge flowpath (surface)
 - Formed discharge nowpath (surface
 - Lagoon discharge flowpath
- >>> Waterway flowpaths (natural)
 - Stormwater flowpaths (sheetflow natural surface)

